

EARTH EMBANKMENTS

DAM NAME Smith-Bybee DATE 10-6-87 PERMIT# _____ FILE# 5-79
 INSPECTOR'S NAME CR King COUNTY Mult DISTRICT 16
 PHOTOS?? (Y or N) Y RESERVOIR ELEV. (S/W CREST) _____

OWNER City of Portland

FOUNDATION (I)
 valley floor _____
 abutments _____
7 right _____
7 left _____

EMBANKMENT (II)
 crest _____
7 upstream _____
7 downstream _____

EMERGENCY SPILLWAY (III)
8 control _____
8 inlet channel _____
8 outlet channel _____
8 slope or walls _____
8 log boom _____

PRIMARY SPILLWAY (IV)
8 inlet _____
8 alignment _____

RESERVOIR AREA (VI)
8 trash control _____
8 geology _____

OUTLET STRUCTURE (V)
8 inlet box _____
8 outlet box _____
8 alignment _____
8 outlet channel _____
8 valve control _____

DOWNSTREAM VALLEY FLOOR (VII)
No hazard change _____
8 terrain assessment _____
8 seepage _____

REINSPECTION DATE 10-88

REMARKS dam failed last year - this info from the
manager of St. John landfill - failure caused
water to come within about 4 feet of the
road around the landfill
Dam has been repaired - patchwork -
Will take a closer look at this next year to
see if any change due to recent reconstruction.