



Figure 1: Photopoint location map



Smith & Bybee Channel Management: Site Photos from Summer 2016



Photo 1: Channel upstream of Water Control Structure, approximately station 2+00 (August 15, 2016)



Photo 2: Existing Derelict Road Crossing (August 15, 2016)



Smith & Bybee Channel Management: Site Photos from Summer 2016



Photo 3: Forested wetland grading area (June 1, 2016)



Photo 4: Existing beaver dam 3 (August 15, 2016)





Photo 5: Existing channel at approx. station 44+00, looking towards lake (August 15, 2016)



Photo 6: Existing channel at approx. station 48+00, looking towards lake (August 15, 2016)